



Mansfield Fire Department

140 E 3rd St
Mansfield, Ohio 44902

INCIDENT

Incident Number MFD2026000469 Incident Date 01/14/2026 NFIRS Number 0000503 Incident Type (111) - Building fire

FDID 70009 Station Station 6 Shift B crew District 3

Initial Dispatch Code SF3 - STRUCTURE FIRE

Alarms 2 Working Fire? Yes COVID-19 was a factor No, COVID-19 was not a factor Critical Incident No Critical Incident Team _____

Temporary Resident Involvement _____

Hazardous Materials Released _____

Action Taken 1
(11) - Extinguishment by fire service personnel

Action Taken 2
(12) - Salvage & overhaul

Action Taken 3
(86) - Investigate

AID

Aid Given/Received _____

(2) - Automatic aid received

Aided Agency _____ Their Incident Number _____

Aiding Agencies
179th A.W. Fire Department

LOCATION

Location Type _____

(1) - Street address

Address _____

41 CAIRNS Road, MANSFIELD, Ohio, 44903

Cross Street, USNG, or Directions _____

Latitude 40.80548800 Longitude -82.51546500 Census Tract _____

Detector Alerted Occupant _____

Property Use _____ Mixed Use _____

(891) - Warehouse

TIMES

PSAP Received <u>19:34:42, 01/14/2026</u>	Dispatch Notified Time <u>19:34:42, 01/14/2026</u>	Alarm Time <u>19:34:42, 01/14/2026</u>
Arrival Time <u>19:42:34, 01/14/2026</u>	Water on Fire Time <u>19:50:00, 01/14/2026</u>	At Patient Time
Loss Stop Time <u>19:53:00, 01/14/2026</u>	Controlled Time <u>19:56:00, 01/14/2026</u>	Last Unit Cleared Time <u>22:09:24, 01/14/2026</u>
Total On Scene Time <u>2 hrs 26 mins 50 sec</u>	Total Incident Time <u>2 hrs 34 mins 42 sec</u>	

COUNTS

Counts Include Aid Received?

No

Suppression:		EMS:		Other:	
Apparatus	Personnel	Apparatus	Personnel	Apparatus	Personnel
<u>10</u>	<u>20</u>	<u>0</u>	<u>0</u>	<u>2</u>	<u>2</u>

LOSS

Property: **Content:**

Estimated Property Losses
\$20000

Estimated Content Losses
\$288000

Estimated Property Value
\$7320380

Estimated Content Value
\$6000000

PERSON/OWNER

Person:

Name



Business Name



Phone



Address



AUTHORIZATION

Report Writer:

Name
CAREY, MICHAEL

Employee Number
MC1706

Assignment
C4

Authorization Date
01/14/2026

Officer in Charge:

Name
CAREY, MICHAEL

Employee Number
MC1706

Assignment
C4

Authorization Date
01/14/2026

Quality Control:

Name


Authorization Date


INCIDENT NARRATIVE

1/14/2026 19:35:22 - SPRINKLER FLOW ALARM-ZONE 5; 1/14/2026 19:37:03 - 2ND CALLER: CLEANING CREW- LARGE FIRE-HEAVY FLAMES- IN THE SHOP; 1/14/2026 19:43:05 - {AFC4} smoke from B side; 1/14/2026 19:43:57 - Everbridge Sent by 1760; 1/14/2026 19:44:40 - E6 going to B side Harrington Memorial; 1/14/2026 19:45:23 - {E1} light smoke inside//; 1/14/2026 19:47:40 - {E2} on the hydrant on the D Side; 1/14/2026 19:47:50 - {AFC4} confirmed fire in the shop//; 1/14/2026 19:49:18 - Cairns is A side//; 1/14/2026 19:51:30 - {E6} fire knocked down//; 1/14/2026 19:53:27 - gas fed fire inside//; 1/14/2026 19:53:52 - Chief 1 recalling personnel; 1/14/2026 19:56:20 - Gas is shut off//; 1/14/2026 19:57:36 - SENDING ALL MEDICAL CALLS TO RCSO FOR BACK-UP-MEDICAL; 1/14/2026 19:58:54 - {AFC4} Fire is out; 1/14/2026 19:59:25 - {AFC4} key holder on scene/ gas lines secured/ working on ventilating the structure//; 1/14/2026 19:59:49 - FC Crow has been advised//; 1/14/2026 20:00:42 - {E4} every door is open to the structure//; 1/14/2026 20:08:13 - {AFC4} Investigator needed; 1/14/2026 20:24:32 - {E6} water is off//; 1/14/2026 21:00:42 - {AFC4} Columbia Gas on Scene//; 1/14/2026 21:02:06 - Columbia Gas responding immediately//

C4 arrived on scene with a full FD assignment to find light smoke visible from the "B"-side of a large commercial warehouse. Cleaning crew on scene verified fire inside and no occupants are inside. E1 crew was advised to enter AD man door as 360 completed.

Interior crews advised fire located near the AB corner, fire was deep seated in a "four stack" row of several box and palatized sink faucets. Fire was being kept in check by a sprinkler.

Crew advise handline needed to extinguish with extensive overhaul. Overhaul operations held until visibility (poor conditions at floor level throughout the large warehouse) could be improved after vent. 1 3/4 hand line stretched from E6 located on B side through man door for extinguishment. Crew advised they had a gas fed fire and to secure gas. Gas secured at meter.

Stop loss and ventilation started utilizing natural vent (bay doors opened on B/D sides. FDC supported by E3 until full extinguishment. Fire Pump and sprinkler system shut down. Four gas from E3 utilized to monitor CO throughout the extensive overhaul operation. All burnt products were removed from the structure out a garage door on the AB corner. Estimated 32 pallets.

FPB called for and investigated, CG called for to secure gas service. All American Sprinkler service called to restore system and at filing of this report both the sprinkler and alarm system were restored.

Created By: CAREY, MICHAEL

Unit Reports

B1

Use	Responding From	Priority
(0) - Other		
Response Delays		
Dispatch Time	Enroute Time	Arrival Time
20:11:58, 01/14/2026	20:18:17, 01/14/2026	20:31:23, 01/14/2026
At Patient Time	Clear Time	In District Time
	22:09:24, 01/14/2026	
Actions Taken:		
Personnel		
MATTHEW SHAFLEY #80328		

E5

Use	Responding From	Priority
(1) - Suppression		
Response Delays		

E5

Dispatch Time <u>19:40:23, 01/14/2026</u>	Enroute Time <u>19:40:24, 01/14/2026</u>	Arrival Time <u>19:44:59, 01/14/2026</u>
At Patient Time <u>22:07:41, 01/14/2026</u>	Clear Time <u>22:07:41, 01/14/2026</u>	In District Time

Actions Taken:

Personnel Count

0**R4**

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		
Dispatch Time <u>19:38:36, 01/14/2026</u>	Enroute Time <u>19:40:19, 01/14/2026</u>	Arrival Time <u>19:49:28, 01/14/2026</u>
At Patient Time <u>21:05:33, 01/14/2026</u>	Clear Time <u>21:05:33, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

JED CRONEBACH, BRADY HITCHCOCK**R3**

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		
Dispatch Time <u>19:38:36, 01/14/2026</u>	Enroute Time <u>19:39:16, 01/14/2026</u>	Arrival Time <u>19:49:10, 01/14/2026</u>
At Patient Time <u>21:05:33, 01/14/2026</u>	Clear Time <u>21:05:33, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

KEATON GRIFFETH, TYLER KING**E4**

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		

E4

Dispatch Time <u>19:38:36, 01/14/2026</u>	Enroute Time <u>19:40:29, 01/14/2026</u>	Arrival Time <u>19:48:22, 01/14/2026</u>
At Patient Time <u>22:09:24, 01/14/2026</u>	Clear Time <u>22:09:24, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

LAWRENCE FIRMI, CHRISTOPHER SACRAMONE**R1**

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		
Dispatch Time <u>19:36:04, 01/14/2026</u>	Enroute Time <u>19:36:51, 01/14/2026</u>	Arrival Time <u>19:43:00, 01/14/2026</u>
At Patient Time <u>20:55:22, 01/14/2026</u>	Clear Time <u>20:55:22, 01/14/2026</u>	In District Time
Actions Taken:		

Personnel

ADAM CUTLIP, COLIN DAWSON**E6**

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		
Dispatch Time <u>19:36:04, 01/14/2026</u>	Enroute Time <u>19:40:27, 01/14/2026</u>	Arrival Time <u>19:43:15, 01/14/2026</u>
At Patient Time <u>22:09:24, 01/14/2026</u>	Clear Time <u>22:09:24, 01/14/2026</u>	In District Time
Actions Taken:		

Personnel

MATTHEW EMERSON, ZACH SMITH, BENJAMIN WALDMAN**R2**

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		

R2

Dispatch Time <u>19:36:04, 01/14/2026</u>	Enroute Time <u>19:36:55, 01/14/2026</u>	Arrival Time <u>19:42:52, 01/14/2026</u>
At Patient Time <u>22:06:35, 01/14/2026</u>	Clear Time <u>22:06:35, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

KASON ANTRICAN, TYRELL WHITE, DOMINIC PLANCK

E3

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		
Dispatch Time <u>19:36:04, 01/14/2026</u>	Enroute Time <u>19:37:34, 01/14/2026</u>	Arrival Time <u>19:46:57, 01/14/2026</u>
At Patient Time <u>21:05:33, 01/14/2026</u>	Clear Time <u>21:05:33, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

NOLAN PROCHASKA, PATRICK RYAN

E1

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		
Dispatch Time <u>19:36:04, 01/14/2026</u>	Enroute Time <u>19:36:51, 01/14/2026</u>	Arrival Time <u>19:42:52, 01/14/2026</u>
At Patient Time <u>22:09:24, 01/14/2026</u>	Clear Time <u>22:09:24, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

TODD TOUSSANT, BRANDON YOUNG

E2

Use <u>(1) - Suppression</u>	Responding From	Priority
Response Delays		

E2

Dispatch Time <u>19:36:04, 01/14/2026</u>	Enroute Time <u>19:36:39, 01/14/2026</u>	Arrival Time <u>19:51:42, 01/14/2026</u>
At Patient Time <u>22:09:24, 01/14/2026</u>	Clear Time <u>22:09:24, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

TREVOR ARNOLD, MICHAEL BLAIR

AFC4

Use <u>(0) - Other</u>	Responding From <u></u>	Priority <u></u>
Response Delays		
Dispatch Time <u>19:36:04, 01/14/2026</u>	Enroute Time <u>19:37:09, 01/14/2026</u>	Arrival Time <u>19:42:34, 01/14/2026</u>
At Patient Time <u>22:09:24, 01/14/2026</u>	Clear Time <u>22:09:24, 01/14/2026</u>	In District Time

Actions Taken:

Personnel

MICHAEL CAREY

Fire Module

SITE INFO

Alarms <u>2</u>	Acres Burned <u></u>	Resident Units In Bldg <u>Not residential</u>	Buildings Involved <u>1</u>
Hydrant Identifier <u></u>	Estimated Water Usage <u>1000</u>		

ON-SITE MATERIALS

Material ID 1 <u>(910) - Containers, packing materials, other</u>	Storage Use ID 1 <u>(3) - Packaged goods for sale</u>
Material ID 2 <u>(622) - Construction and home improvement products</u>	Storage Use ID 2 <u>(1) - Bulk storage or warehousing</u>

IGNITION

Area of Origin <u>(45) - Shipping/receiving area; loading area, dock or bay</u>	Heat Source <u>(12) - Radiated or conducted heat from operating equipment</u>	Fire Confined to Item? <u></u>
Item First Ignited <u>(51) - Box, carton, bag, basket, barrel</u>		

IGNITION

Type of Material First Ignited

(68) - Cardboard

Cause of Ignition

(5) - Cause under investigation

Factors Contributing to Ignition 1

(UU) - Undetermined

Human Factors Contributing to Ignition

(N) - None

Est. Age of Person Involved

Gender of Person Involved

EQUIPMENT

Equipment Involved in Ignition

(142) - Heater, catalytic

Equipment Power Source

(21) - Natural gas or other lighter-than-air gas

Equipment Portability

(2) - Stationary

Brand

Model

Serial Number

Year

STRUCTURE

Structure Type

(1) - Enclosed building

Stories Above Grade

1

Stories Below Grade

0

Building Status

(2) - In normal use

Length

550 ft

Width

340 ft

Total Square Feet

187000 sq ft

Story of Fire Origin

1

Fire Spread

(4) - Confined to building of origin

Item Contributing Most to Flame Spread

Type of Material

Number of Stories with Damage

Minor Damage

1

Significant Damage

0

Heavy Damage

0

Extreme Damage

0

Total Stories

1

PROTECTIVE SYSTEMS

Presence of Detector

(1) - Present

Detector Type

(1) - Smoke

Power Supply

(7) - Multiple detectors and power supplies

Detector Operations

(2) - Detector operated

Effectiveness (/Failure Reason)

(1) - Detector alerted occupants, occupants responded

Presence of Auto Extinguishing System

(1) - Present

System Type

(1) - Wet-pipe sprinkler system

 **PROTECTIVE SYSTEMS**

System Operation

(1) - System operated and was effective

of Sprinklers

1

Reason for System Failure
