



Mansfield Fire Department

140 E 3rd St
Mansfield, Ohio 44902

INCIDENT

Incident Number 24003909	Incident Date 05/01/2024	NFIRS Number 0003866	Incident Type (116) - Fuel burner/boiler malfunction, fire confined
------------------------------------	------------------------------------	--------------------------------	---

FDID 70009	Station Station 1	Shift B crew	District 6
----------------------	-----------------------------	------------------------	----------------------

Initial Dispatch Code
STRUCTURE FIRE

Alarms	Working Fire? Yes	COVID-19 was a factor No, COVID-19 was not a factor	Critical Incident No	Critical Incident Team
--------	-----------------------------	---	--------------------------------	------------------------

Temporary Resident Involvement

Hazardous Materials Released

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(64) - Shut down system

AID

Aid Given/Received

(N) - None

LOCATION

Location Type

(1) - Street address

Address

913 BOWMAN Street, MANSFIELD, Ohio, 44903

Cross Street, USNG, or Directions

Latitude

40.78483000

Longitude

-82.52384000

Census Tract

Detector Alerted Occupant

(U) - Unknown

Property Use

(984) - Industrial plant yard - area

Mixed Use

TIMES

PSAP Received

04:05:38, 05/01/2024

Dispatch Notified Time

04:05:38, 05/01/2024

Alarm Time

04:05:38, 05/01/2024

Arrival Time

04:12:29, 05/01/2024

Water on Fire Time

At Patient Time

⌚ TIMES

Loss Stop Time	Controlled Time	Last Unit Cleared Time
_____	_____	05:52:45, 05/01/2024
Total On Scene Time	Total Incident Time	
1 hrs 40 mins 16 sec	1 hrs 47 mins 7 sec	

📊 COUNTS

Counts Include Aid Received?
No

Suppression:		EMS:		Other:	
Apparatus	Personnel	Apparatus	Personnel	Apparatus	Personnel
6	10	0	0	2	2

💰 LOSS

Property:	Content:
Estimated Property Losses	Estimated Content Losses
\$5000	\$1000
Estimated Property Value	Estimated Content Value
\$	\$

👤 PERSON/OWNER

📄 AUTHORIZATION

Report Writer:

Name	Employee Number	Assignment	Authorization Date
CAREY, MICHAEL	MC1706	_____	05/01/2024

Officer in Charge:

Name	Employee Number	Assignment	Authorization Date
CAREY, MICHAEL	MC1706	_____	05/01/2024

Quality Control:

Name	Authorization Date
_____	_____

📝 INCIDENT NARRATIVE

RESCUE 1 BACK AT LOCATION [05/01/24 05:26:57 ESAUNDERS] SITUATION CONTAINED- COOLING DOWN THE REST OF THE AREA [05/01/24 04:34:24 ESAUNDERS] EVERBRIDGE WAS SENT [05/01/24 04:33:27 ESAUNDERS] GAS SHUT OFF [05/01/24 04:23:26 ESAUNDERS] COLUMBIA GAS ADVISED / GAS IS SHUTOFF JUST REQUESTING A RESPONSE [05/01/24 04:23:25 KBURTON] FC CROW WAS ADVISED [05/01/24 04:21:52 ESAUNDERS] NATURAL GAS LINE [05/01/24 04:21:44 ESAUNDERS] INSIDE PLANT- MELT SHOP [05/01/24 04:05:59 ESAUNDERS]

C-4 ARRIVED ON SCENE WITH A FULL FD RESPONSE TO FIND OCCUPANTS EVACUATED FROM THE MELT SHOP. LARGE VOLUME OF SMOKE COULD BE SEEN COMING FROM A 400X100 OPEN STEEL BUILDING. LINE SUPERVISOR STATED HE BELIEVED THE HYDRAULIC LINES TO A KILN HAD BURST AND CAUGHT FIRE, FURTHER STAED THERE WERE LARGE NATURAL GASLINES TO THE KILN AND THE FIRE MAY HAVE STARTED TO INVOLVE THE LINES.

360 FOUND A KILN LOCATED IN THE CENTER OF THE STRUCTURE HEAVILY INVOLVED A PRESSURIZED GAS FED FIRE. CREWS WERE ADVISED TO NOT ENGAGE UNTIL GAS WAS SECURED. SHUT OFF VALVES WERE LOCATED AT THE KILN AND NOT ACCESSIBLE DUE TO EXRTREME HEAT. MAINTENANCE CREWS WORKED TO SAFELY SECURE UTILITIES TO AREA INVOLVED ONLY.

INCIDENT NARRATIVE

UTILITIES SECURED, CREWS WERE ABLE TO CONTAIN AND EXTINGUISH REMAINING FIRE LOCATED ON THE BACK SIDE OF SMELTING POT/KILN. MAINTENANCE CREWS UTILIZED A MAN LIFT TO EXTINGUISH ELECTRICAL CONDUIT FIRE LOCATED ABOVE KILN . DRY CHEM EXT USED ON CONDUIT. SUPPLY LINE LAID BUT NOT CHARGED. ONE LINE PULLED FROM E-6 FOR EXPOSURE. MAIN FIRE EXTINGUISHED WITH HOUSE LINES. TIC UTILIZED TO MONITOR STRUCTURAL STEEL TEMP.

TOM HYPES, PLANT MANAGER (419) 569-3258 ON SCENE. ADVISED THEY WILL CONTINUE TO MONITOR AS KILN AND AREA CONTINUES TO COOL. FURTHER ADVISED NO STOP IN PRODUCTION. OPERATIONS WILL BE BACK TO FULL CAPACITY AS SOON AS REPAIRS TO KILN AND CONDUIT MADE.

Created By:

Unit Reports

R1

Use (1) - Suppression	Responding From	Priority Emergent
---------------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

Dispatch Time 04:07:17, 05/01/2024	Enroute Time 04:08:45, 05/01/2024	Arrival Time 04:15:20, 05/01/2024
--	---	---

At Patient Time	Clear Time 05:15:47, 05/01/2024	In District Time
-----------------	---	------------------

Actions Taken:

Personnel
DEVIN RAMEY, TREVOR ARNOLD

AFC4

Use (0) - Other	Responding From	Priority
---------------------------	-----------------	----------

Response Delays

Dispatch Time 04:07:17, 05/01/2024	Enroute Time 04:08:31, 05/01/2024	Arrival Time 04:12:29, 05/01/2024
--	---	---

At Patient Time	Clear Time 05:42:32, 05/01/2024	In District Time
-----------------	---	------------------

Actions Taken:

Personnel
MICHAEL CAREY

E1

Use (1) - Suppression	Responding From	Priority
---------------------------------	-----------------	----------

Response Delays

E1

Dispatch Time 04:07:17, 05/01/2024 Enroute Time 04:08:36, 05/01/2024 Arrival Time 04:14:24, 05/01/2024

At Patient Time _____ Clear Time 05:27:05, 05/01/2024 In District Time _____

Actions Taken:

Personnel
MATTHEW EMERSON

E2

Use (1) - Suppression Responding From _____ Priority _____

Response Delays

Dispatch Time 04:07:17, 05/01/2024 Enroute Time 04:07:42, 05/01/2024 Arrival Time 04:16:29, 05/01/2024

At Patient Time _____ Clear Time 05:52:45, 05/01/2024 In District Time _____

Actions Taken:

Personnel
ISAIAH FINLEY, MARK SIEVING

R2

Use (1) - Suppression Responding From _____ Priority _____

Response Delays

Dispatch Time 04:07:17, 05/01/2024 Enroute Time 04:13:22, 05/01/2024 Arrival Time 04:16:37, 05/01/2024

At Patient Time _____ Clear Time 05:43:51, 05/01/2024 In District Time _____

Actions Taken:

Personnel Count
0

E3

Use (1) - Suppression Responding From _____ Priority _____

Response Delays

E3

Dispatch Time <u>04:07:17, 05/01/2024</u>	Enroute Time <u>04:08:48, 05/01/2024</u>	Arrival Time <u>04:18:13, 05/01/2024</u>
--	---	---

At Patient Time _____	Clear Time <u>05:20:25, 05/01/2024</u>	In District Time _____
--------------------------	---	---------------------------

Actions Taken:

Personnel
JERMAINE LANIER, TIMOTHY KASH

TO

Use <u>(0) - Other</u>	Responding From _____	Priority _____
---------------------------	--------------------------	-------------------

Response Delays

Dispatch Time <u>04:07:17, 05/01/2024</u>	Enroute Time <u>04:08:56, 05/01/2024</u>	Arrival Time <u>04:13:11, 05/01/2024</u>
--	---	---

At Patient Time _____	Clear Time <u>05:43:10, 05/01/2024</u>	In District Time _____
--------------------------	---	---------------------------

Actions Taken:

Personnel
DAVID COMPTON

E6

Use <u>(1) - Suppression</u>	Responding From _____	Priority _____
---------------------------------	--------------------------	-------------------

Response Delays

Dispatch Time <u>04:07:17, 05/01/2024</u>	Enroute Time <u>04:09:16, 05/01/2024</u>	Arrival Time <u>04:12:30, 05/01/2024</u>
--	---	---

At Patient Time _____	Clear Time <u>05:43:02, 05/01/2024</u>	In District Time _____
--------------------------	---	---------------------------

Actions Taken:

Personnel
BENJAMIN WALDMAN, BRADLEY BURWELL, JUSTIN MEILINGER

 **Fire Module**

① SITE INFO

Alarms _____	Acres Burned _____	Resident Units In Bldg <u>Not residential</u>	Buildings Involved <u>1</u>
-----------------	-----------------------	--	--------------------------------

📍 SITE INFO

Hydrant Identifier _____ Estimated Water Usage
 _____ **500** _____

🔥 IGNITION

Area of Origin
(64) - Incinerator area _____

Heat Source
(42) - Molten, hot material _____

Item First Ignited _____ Fire Confined to Item?
(66) - Pipe, duct, conduit, hose _____ **No** _____

Type of Material First Ignited
(11) - Natural gas _____

Cause of Ignition
(3) - Failure of equipment or heat source _____

Factors Contributing to Ignition 1
(UU) - Undetermined _____

Human Factors Contributing to Ignition
(N) - None _____

Est. Age of Person Involved _____ Gender of Person Involved _____

⚙️ EQUIPMENT

Equipment Involved in Ignition
(000) - Other equipment involved in ignition _____

Equipment Power Source _____ Equipment Portability
(00) - Power source, other _____ **(1) - Portable** _____

Brand _____	Model _____	Serial Number _____	Year _____
-------------	-------------	---------------------	------------

🏠 STRUCTURE

Structure Type _____

Stories Above Grade _____	Stories Below Grade _____	Building Status _____
---------------------------	---------------------------	-----------------------

Length _____	Width _____	Total Square Feet _____	Story of Fire Origin _____
--------------	-------------	-------------------------	----------------------------

Fire Spread _____

Item Contributing Most to Flame Spread _____	Type of Material _____
--	------------------------

Number of Stories with Damage

Minor Damage _____	Significant Damage _____	Heavy Damage _____	Extreme Damage _____	Total Stories _____
--------------------	--------------------------	--------------------	----------------------	---------------------

PROTECTIVE SYSTEMS

Presence of Detector	Detector Type	
_____	_____	_____
Power Supply		Detector Operations
_____	_____	_____
Effectiveness (/Failure Reason)		

Presence of Auto Extinguishing System		System Type
_____	_____	_____
System Operation	# of Sprinklers	Reason for System Failure
_____	_____	_____

Casualty

FIRE SERVICE CASUALTY #1

Injured Person

Name	Gender	Date of Birth	Age
_____	(1) - Male	_____	_____

Identification #	Service Type	Usual Assignment
_____	_____	_____

of Responses in Last 24 Hours

Injury Info

Injury Time and Date	Severity
05:30:00, 05/01/2024	(2) - First aid only

Physical Condition Just Prior	Activity at Time of Injury
_____	(75) - Picking up tools, equipment, or hose on scene

Cause of Firefighter Injury

(U) - Undetermined

Object Involved in Injury

(NN) - None

Factor Contributing to Injury

Primary Apparent Symptom	Primary Area of Body Injured
(53) - Nausea	_____

Taken to

Injury Location

Where Injury Occurred	Inside or Outside a Structure	Story
(6) - At scene, outside structure	(2) - Outside of structure	_____

Specific Location	Vehicle Type
_____	_____

FIRE SERVICE CASUALTY #1

Remarks